

FIG. 1

PRIOR ART




FIG. 2

PRIOR ART




FIG. 3




FIG. 4




FIG. 5





FIG. 6






FIG. 7A




FIG. 7B

FIG. 8A




FIG. 8B




FIG. 8C




FIG. 9A




FIG. 9B




FIG. 9C





FIG. 9D




FIG. 9E




FIG. 9F

FIG. 10(a)




FIG. 10(b)




FIG. 10(c)




FIG. 10(d)




FIG. 11




FIG. 12(a)




FIG. 12(b)




FIG. 13




FIG. 14(a)

$m=2$




FIG. 14(b)

$m=3$



FIG. 14(c)

$m=4$





FIG. 14(d)

$m=5$



FIG. 14(e)

$m=6$



$m=7$






FIG. 14(f)

$m=8$



$m=9$



$m=10$




FIG. 14 (g)

FIG. 14(h)

FIG. 14(i)

FIG. 15(a)

$\alpha = 0.1$




FIG. 15(b)

$\alpha = 0.3$






FIG. 15(c)

$\alpha = 0.5$



$\alpha = 0.7$



$\alpha = 0.9$




FIG 15(d)

FIG. 15(e)

FIG.

16(a)




FIG.

16(b)




FIG. 17(a)




FIG. 17(b)




FIG. 17(c)

FIG. 17(d)

FIG. 18(a)




FIG. 18(b)





FIG. 18(c)






FIG. 19




FIG. 20

FIG.21




FIG.22




FIG.23

FIG.24

